

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

**** SBFCA currently has operation and maintenance obligations during project construction and closeout.**

Levee District No. 0009 (Sutter County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter County, Feather River	Right	6.25	10/04/2016 10/04/2016	Sterling York

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_LD0009_01_s_2013_4				
Comment Code					
Inspector Comment					
LD 9 has flood fight supplies on hand and coordinates with other local levee districts in the flood fight supply staging program.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_LD0009_01_s_2013_5				
Comment Code					
Inspector Comment					
The levee district has stated in the past that they have a copy of the O&M manuals.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

**** SBFCA currently has operation and maintenance obligations during project construction and closeout.**

Levee District No. 0009 (Sutter County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter County, Feather River	Right	6.25	10/04/2016 10/04/2016	Sterling York

LM Start		Rating **	A	Issue No.	6	
LM End		Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start	End	
Item	Flood Preparedness & Training				°	
					°	
DWR ID	DWR_LD0009_01_s_2013_6					
Comment Code						
Inspector Comment						
The district has attended the Flood Fight class put on by RD 784 and DWR.						

No Photos

LM Start	0.01	Rating **	A	Issue No.	16
LM End	6.24	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.168919 °	39.255752 °
				-121.622539 °	-121.636363 °
DWR ID	DWR_LD0009_01_f_2016_16				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 2 : FA_2016_LD0009_202_16_20161006_00026.jpg



View of well maintained annual vegetation that is mowed on the landside looking downstream. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**** SBFCA currently has operation and maintenance obligations during project construction and closeout.**


Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter County, Feather River	Right	6.25	10/04/2016 10/04/2016	Sterling York

Photo 2 of 2 : FA_2016_LD0009_202_16_20161006_00028.jpg



View of well maintained annual vegetation that was burned on the
roadside. Photo taken on 10/06/2016.

Photo 1 of 2 : FA_2016_LD0009_202_17_20161006_00029.jpg



View of well maintained annual vegetation that is mowed on the waterside looking downstream. Fall 2016.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	N/A : Not Applicable A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**** SBFCA currently has operation and maintenance obligations during project construction and closeout.**


Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter County, Feather River	Right	6.25	10/04/2016 10/04/2016	Sterling York

Photo 2 of 2 : FA_2016_LD0009_202_17_20161006_00034.jpg



View of well maintained annual vegetation that was burned on the
waterside looking downstream. Fall 2016.

Photo 1 of 1 : FA_2016_LD0009_202_18_20161006_00042.jpg



View of rodent holes that need to be backfilled, no sign of rodents at time of inspection. Fall 2016.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	N/A : Not Applicable A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

**** SBFCA currently has operation and maintenance obligations during project construction and closeout.**

Levee District No. 0009 (Sutter County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter County, Feather River	Right	6.25	10/04/2016 10/04/2016	Sterling York

LM Start	5.32	Rating **	A/W	Issue No.	19
LM End	5.32	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.242582 °	39.242582 °
				-121.637032 °	-121.637032 °
DWR ID	DWR_LD0009_01_f_2015_19				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
This rodent site has been repaired by the LMA and there is no new evidence of rodent activity at this location. The picture was taken during the 2015 Fall Inspection.					

Photo 1 of 1 : FA_2016_LD0009_202_19_20161006_00040.jpg



View of area on the landside where rodent holes have been repaired.

LM Start	5.71	Rating **	C	Issue No.	21
LM End	5.71	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.248009 °	39.248009 °
				-121.637306 °	-121.637306 °
DWR ID	DWR_LD0009_01_f_2015_21				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					
Tree stump has been removed. Fall 2016.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---